

FIG. 1




FIG. 2




FIG. 3




FIG. 6





FIG. 4

003807 500075380






FIG. 7

- ① ROTATE HANDLE TO EJECT
- ② LIFT ASSEMBLY TO REMOVE




FIG. 9





FIG. 8






FIG. 10A




FIG. 11




FIG. 12




FIG. 13




FIG. 13a





FIG. 14

FIG. 15






FIG. 17




FIG. 18
Locked in for
Operation




FIG. 19




FIG. 20




FIG. 21